




M 5.4, 113 km S of Champerico, GuatemalaOrigin Time: 2021-08-24 16:16:42 UTC (Tue 10:16:42 local) Location: 13.2729° N 91.8658° W Depth: 10.0 km

PAGER Version 5

Created: 2 weeks, 1 day after earthquake



Estimated Population Exposed to Earthquake Shaking

ESTIMATED POPULATION EXPOSURE (k=x1000)		_*	11,542k	0	0	0	0	0	0	0
ESTIMATED MODIFIED MERCALLI INTENSITY		I	11-111	IV	V	VI	VII	VIII	IX	X+
PERCEIVED SHAKING		Not felt	Weak	Light	Moderate	Strong	Very Strong	Severe	Violent	Extreme
POTENTIAL DAMAGE	Resistant Structures	None	None	None	V. Light	Light	Moderate	Mod./Heavy	Heavy	V. Heavy
	Vulnerable Structures	None	None	None	Light	Moderate	Mod./Heavy	Heavy	V. Heavy	V. Heavy

^{*}Estimated exposure only includes population within the map area.

Population Exposure

population per 1 sq. km from Landscan

92.8 13.5°N 12.2°N

placted City Evangura

Seie	cted City Exposure	
rom G	eoNames.org	
MMI	City	Population
Ш	Champerico	8k
Ш	Nueva Concepcion	11k
Ш	San Jose La Maquina	<1k
Ш	Tiquisate	18k
Ш	La Gomera	24k
Ш	Puerto San Jose	19k
Ш	Escuintla	103k
Ш	Quetzaltenango	132k
II	Chimaltenango	82k
II	Totonicapan	70k
II	Guatemala City	995k

bold cities appear on map.

(k = x1000)

Structures

Overall, the population in this region resides in structures that are a mix of vulnerable and earthquake resistant construction. The predominant vulnerable building types are mud wall and adobe block with concrete bond beam construction.

Historical Earthquakes

Date	Dist.	Mag.	Max	Shaking
(UTC)	(km)		MMI(#)	Deaths
2001-02-17	303	4.1	V(2,250k)	1
2001-05-08	329	5.7	VII(562k)	1
1976-02-04	369	7.5	IX(80k)	23k

Recent earthquakes in this area have caused secondary hazards such as landslides that might have contributed to losses.